
QY20 手动圆角机使用手册

QY20 Desktop Corner Cutter Illustration



标准配备 Standard Parts&Accessories

Standard Parts&Accessories		-EC
校正板一片	六角板手二支	刀片一个
One alignment board	Two hex wrenches	One blade
American de la constant de la consta	TEC TEC	NITEC
磁板一片	铜片一个	压纸工具一个
One magnetic plate	One copper blade	One paper clamp
INI.		NISIC

使用安全注意事项 Operational Attention Matters

手指远离刀具切角的区域	Keep fingers away from cutting area.	
这不是一台玩具,避免让幼童拿去玩耍	Avoid reach of children It is not a toy!	
不可切订书针或文件夹或其它任何非纸制品	Do not cut staples, paper clips and other	
	metal objects.	
换刀时请注意刀口锐利部分	When changing the blade, please be aware of	
	the blade.	
刀具口应小心保护, 不可碰撞坚硬的物质	Blade should be carefully protected and can	
	not be any hard object.	

Operational Instructions

Step 1



Open the package and take out the machine.

UNITEC



Step 2 Install the magnetic board at the bottom of the machine.

NITEC

Step 3



Open the tools box and take out the hex wrenches.

Install the handle in the direction shows in the picture.

Step 4



Take off the paper clamp.
Push handle downward.
Calibrate and fix the copper blade as the picture shows.

UNITEC

Step 5



Calibrate and fix the side guides by using the alignment board.
Install the paper clamp.

UNITEC

Step 6



Place sheets and align them tightly to both sides of the side guides, push handle downward to cut.

UNITEC

